ASPEN CRACH: ATC AUDIO MUST CREDIT LIVEATC.NET

07:39	DENVER CENTER CLEARS N115WF APPROACH TO ASPEN
08:22	PREVIOUS LANDING PLANE REPORTS WIND SHEAR, A 12 KT GAIN ON 3 MILE APPROACH
08:42	DENVER CENTER HANDS OVER PLANE TO ASPEN TOWER
10:01	TOWER ADVISES WIND 320 DEG AT 12KTS, GUSTING TO 25KTS CLEARED TO LAND
10:21	ANOTHER PREVIOUS LANDING PLANE REPORTS A 20KT GAIN WIND SHEAR
10:34	TOWER ADVISES N115WF OF PREVIOUS REPORT, ADVISES CAUTION
10:36	N115WF ACKNOWLEDGES. "ROGER."
11:09	N115WF ADVISES MISSED APPROACH. 33 KT TAILWIND
11:15	TOWER ADVISES EXECUTE PUBLISHED MISSED APPROACH PROCEDURE
11:31	PILOT ORDERED TO EXPIDITE CLIMB 10 16,000
12:44	PILOT SOUNDS CONFUSED OR BUSY BUT CLIMBING TO 16,000
12:52	ASPEN DEPARTURE ASKS PILOTS INTENTIONS
	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT
L2:58 FAILW	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT
L2:58 FAILW	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT IND PILOT FLUBS RUNWAY NUMBER, APOLOGIZES
L2:58 FAILW L3:00 L6:56	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT IND PILOT FLUBS RUNWAY NUMBER, APOLOGIZES
L2:58 FAILW L3:00 L6:56	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT IND PILOT FLUBS RUNWAY NUMBER, APOLOGIZES CONTROLLER HAS TO CLARIFY LANDING INSTRUCTIONS TO PILOT
12:58 FAILW 13:00 16:56 17:52	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT IND PILOT FLUBS RUNWAY NUMBER, APOLOGIZES CONTROLLER HAS TO CLARIFY LANDING INSTRUCTIONS TO PILOT CONTROLLER ADVISES PILOT TO CONTACT ASPEN TOWER
12:58 FAILW 13:00 16:56 17:52 19:17 19:33	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT IND PILOT FLUBS RUNWAY NUMBER, APOLOGIZES CONTROLLER HAS TO CLARIFY LANDING INSTRUCTIONS TO PILOT CONTROLLER ADVISES PILOT TO CONTACT ASPEN TOWER ASPEN TOWER ADVISES PILOT HE'S NUMBER ONE TO LAND ON RUNWAY 15 TOWER ADVISES PILOT OF OTHER TRAFFIC. RESPONSE IS "IFR" I BELIEVE THIS MEANS
12:58 FAILW 13:00 16:56 17:52 19:17 19:33	ADVISES ASPEN DEPARTURE GOING TO DO ANOTHER APPROACH. HAD 30KT IND PILOT FLUBS RUNWAY NUMBER, APOLOGIZES CONTROLLER HAS TO CLARIFY LANDING INSTRUCTIONS TO PILOT CONTROLLER ADVISES PILOT TO CONTACT ASPEN TOWER ASPEN TOWER ADVISES PILOT HE'S NUMBER ONE TO LAND ON RUNWAY 15 TOWER ADVISES PILOT OF OTHER TRAFFIC. RESPONSE IS "IFR" I BELIEVE THIS MEANS HE CAN'T SEE THE OTHER PLANE DUE TO WEATHER CONDITIONS. TOWER GIVES PILOT A WX REPORT. WINDS 330 DEG AT 16 KTS WITH 3 MINUTE

COMMOTION IN BKGD OF CONTROLLER AND ANOTHER PILOT HE'S TALKING WITH

- 22:49 TOWER CLEARS FIREFIGHTING TRUCK "STRYKER" TO "DOWNED AIRCRAFT."
- 23:59 ANOTHER FIRE APPARTUS CLEARED TO DOWNED AIRCRAFT
- 26:50 ANOTHER AIRCRAFT ON GROUND INQUIRES ABOUT SMOKE. TOLD "INCIDENT HERE ON THE RUNWAY"
- 27:15 ANOTHER AIRCRAFT (N455QS) "HAPPENED RIGHT IN FRONT OF US"
- 27:35 ANOTHER PILOT IDENTIFIES THE DOWNED AIRCRAFT AS A "CHALLENGER"
- 29:05 CONTROLLER ANNOUNCEMENT: RUNWAY CLOSED DUE TO INCIDENT