

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
September 04, 2012 10:18:39 AM
Test End Date/Time: Tuesday,
September 04, 2012 10:27:59 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: PAUL VINCENT

Vehicle Information

Vehicle Type: School Bus
Year: 1990
Make: INTERNATIONAL
Model: WAYNE
VIN: 1HVBBCFN6LH236577
License Plate: 1057180
LP State: TX
Odometer Status: READABLE
Odometer Reading: 205969
Corrected Odometer:
Insurance Expiration: 07/01/2013
Insurance Mileage Expiration:

Inspection Information

Certificate #: G21189703
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

*NEW STICKER # G26891170
8-13-13 @ 208,418
CARL PATTON*

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Wednesday,
December 18, 2013 6:51:28 AM
Test End Date/Time: Wednesday,
December 18, 2013 6:54:13 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: CHRIS CHADDICK

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS
Model: MVP
VIN: 1T7HT4B21X1070131
License Plate: 755654
LP State: TX
Odometer Status: READABLE
Odometer Reading: 216611
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942963
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T002

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October
31, 2013 3:14:18 PM
Test End Date/Time: Thursday, October
31, 2013 3:16:37 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS
Model: THOMAS
VIN: 1T7HT4B23X1070129
License Plate: 755653
LP State: TX
Odometer Status: READABLE
Odometer Reading: 220227
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942923
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, January 31,
2014 1:06:28 AM
Test End Date/Time: Friday, January 31,
2014 1:10:14 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MARCONY RUIZ

Inspection Information

Certificate #: G30942989
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: IC
Model: CROWN
VIN: 1HVBBABNOTH417815
License Plate: 1057108
LP State: TX
Odometer Status: READABLE
Odometer Reading: 259388
Corrected Odometer:
Insurance Expiration: 07/01/2015
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
November 12, 2013 1:21:15 PM

Test End Date/Time: Tuesday, November
12, 2013 1:22:41 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR
POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30942933

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 1999

Make: THOMAS

Model: THOMAS MVP

VIN: 1T7HT4B20X1070136

License Plate: 755658

LP State: TX

Odometer Status: READABLE

Odometer Reading: 204639

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, August 31,
2012 7:37:52 AM
Test End Date/Time: Friday, August 31,
2012 7:50:25 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus
Year: 1990
Make: IC
Model: 3800
VIN: 1HVBBCFNXLH236579
License Plate: 1057181
LP State: TX
Odometer Status: READABLE
Odometer Reading: 187136
Corrected Odometer:
Insurance Expiration: 07/01/2013
Insurance Mileage Expiration:

Inspection Information

Certificate #: G21189704
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

NEW STICKER # G26891166
8-13-13 @ 189,855 miles
ALAN TRICALLUM

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
December 09, 2013 11:48:58 AM
Test End Date/Time: Monday, December
09, 2013 11:50:27 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30942957
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS
Model: THOMAS MVP
VIN: 1T7HT4B28X1070126
License Plate: 755651
LP State: TX
Odometer Status: READABLE
Odometer Reading: 212659
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, March 07,
2014 8:35:39 AM
Test End Date/Time: Friday, March 07,
2014 8:42:29 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVRJABR01A911720
License Plate: 1057248
LP State: TX
Odometer Status: READABLE
Odometer Reading: 191911
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943019
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, January
07, 2014 5:16:23 PM
Test End Date/Time: Tuesday, January
07, 2014 5:22:36 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS
Model: THOMAS
VIN: 1T7HT4B22X1070140
License Plate: 757185
LP State: TX
Odometer Status: READABLE
Odometer Reading: 155933
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942967
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
November 18, 2013 8:22:34 PM

Test End Date/Time: Monday, November
18, 2013 8:26:25 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR
POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G30942945

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 1999

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B24X1070124

License Plate: 804281

LP State: TX

Odometer Status: READABLE

Odometer Reading: 186849

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, October
14, 2013 3:49:18 PM
Test End Date/Time: Monday, October
14, 2013 3:54:36 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS MVP
Model: THOMAS
VIN: 1T7HT4B25X1070133
License Plate: 839313
LP State: TX
Odometer Status: READABLE
Odometer Reading: 179879
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942906
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
November 18, 2013 8:08:30 PM

Test End Date/Time: Monday, November
18, 2013 8:11:01 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR
POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Inspection Information

Certificate #: G30942944

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 1999

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B26X1070125

License Plate: 839788

LP State: TX

Odometer Status: READABLE

Odometer Reading: 218011

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, March 17,
2014 8:59:26 AM
Test End Date/Time: Monday, March 17,
2014 9:01:29 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G30943021
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIONAL
Model: AMTRAN
VIN: 1HVBJABR11A911726
License Plate: 1057109
LP State: TX
Odometer Status: READABLE
Odometer Reading: 199665
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April
23, 2014 1:24:27 AM
Test End Date/Time: Wednesday, April
23, 2014 1:29:15 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: PAUL VINCENT

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBABN31A911796
License Plate: 807886
LP State: TX
Odometer Status: READABLE
Odometer Reading: 194755
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943048
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T017

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, April 28,
2014 2:19:28 AM
Test End Date/Time: Monday, April 28,
2014 2:23:40 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: CARL PATTON

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBRA51A911797
License Plate: 1091343
LP State: TX
Odometer Status: READABLE
Odometer Reading: 186872
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943049
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
09, 2014 2:48:57 PM
Test End Date/Time: Thursday, January
09, 2014 2:50:53 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30942968
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 2004
Make: IC CORP
Model: 9600
VIN: 4DRBRABNX4B971820
License Plate: 868381
LP State: TX
Odometer Status: READABLE
Odometer Reading: 159524
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
23, 2014 1:17:54 PM
Test End Date/Time: Thursday, January
23, 2014 1:21:34 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2004
Make: IHC
Model: AMTRAN
VIN: 4DRBRABN34B971822
License Plate: 868383
LP State: TX
Odometer Status: READABLE
Odometer Reading: 142755
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942974
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, July 22,
2014 12:24:48 AM
Test End Date/Time: Tuesday, July 22,
2014 12:27:55 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 1989
Make: THOMAS
Model: THOMAS
VIN: 1T7C3D832K1367301
License Plate: 1037499
LP State: TX
Odometer Status: READABLE
Odometer Reading: 276450
Corrected Odometer:
Insurance Expiration: 07/01/2015
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707125
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, March
04, 2014 5:32:34 AM

Test End Date/Time: Tuesday, March 04,
2014 5:34:37 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR
POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2004

Make: IC CORP

Model: 9600

VIN: 4DRBRAANX4B971737

License Plate: 870814

LP State: TX

Odometer Status: READABLE

Odometer Reading: 157918

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943015

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, March 28,
2014 10:43:34 AM
Test End Date/Time: Friday, March 28,
2014 10:45:20 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3700
VIN: 1HVBBABN2TH417816
License Plate: 1057101
LP State: TX
Odometer Status: READABLE
Odometer Reading: 267960
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943035
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
February 27, 2014 2:32:07 AM

Test End Date/Time: Thursday, February
27, 2014 2:34:39 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR
POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Inspection Information

Certificate #: G30943010

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 1996

Make: IHC

Model: CARPENTER

VIN: 1HVBBABN4TH417817

License Plate: 1057100

LP State: TX

Odometer Status: READABLE

Odometer Reading: 248409

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
09, 2014 3:03:21 PM
Test End Date/Time: Thursday, January
09, 2014 3:05:48 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30942970
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3700
VIN: 1HVBBABN6TH417818
License Plate: 1057099
LP State: TX
Odometer Status: READABLE
Odometer Reading: 205802
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
30, 2014 3:24:57 AM
Test End Date/Time: Thursday, January
30, 2014 3:28:21 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3800
VIN: 1HVBBABN6TH417821
License Plate: 1057045
LP State: TX
Odometer Status: READABLE
Odometer Reading: 184264
Corrected Odometer:
Insurance Expiration: 07/01/2015
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942985
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, March
27, 2014 6:41:23 AM
Test End Date/Time: Thursday, March
27, 2014 6:45:04 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3700
VIN: 1HVBBABN8TH417819
License Plate: 1057112
LP State: TX
Odometer Status: READABLE
Odometer Reading: 237764
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943030
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, March 18, 2014 11:09:44 AM

Test End Date/Time: Tuesday, March 18, 2014 11:12:23 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30943023

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 1996

Make: IHC

Model: CARPENTER

VIN: 1HVBBABL0TH417831

License Plate: 1057113

LP State: TX

Odometer Status: READABLE

Odometer Reading: 208285

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Vehicle Inspection Connection (VIC)

**Texas Department of Public Safety
Vehicle Inspection Report**

Test Start Date/Time: Friday, March 28,
2014 10:43:34 AM

Test End Date/Time: Friday, March 28,
2014 10:45:20 AM

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30943035

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Overall Result: Pass

Vehicle Information

Vehicle Type: School Bus

Year: 1996

Make: INTERNATIO

Model: 3700

VIN: 1HVBBABN2TH417816

License Plate: 1057101

LP State: TX

Odometer Status: Readable

Odometer Reading: 267960

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

T046

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, March 25, 2014 8:34:10 AM

Test End Date/Time: Tuesday, March 25, 2014 8:36:43 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 1996

Make: INTERNATIO

Model: 3800

VIN: 1HVBBABL2TH417832

License Plate: 1065017

LP State: TX

Odometer Status: READABLE

Odometer Reading: 169630

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943027

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, March
27, 2014 8:29:38 AM
Test End Date/Time: Thursday, March
27, 2014 8:31:34 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS
Model: THOMAS MVP
VIN: 1T7HT4B22X1070137
License Plate: 1057098
LP State: TX
Odometer Status: READABLE
Odometer Reading: 189151
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943032
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T048

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 11:03:16 AM
Test End Date/Time: Thursday, May 01,
2014 11:05:05 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3700
VIN: 1HVBBABLXTH417822
License Plate: 1057104
LP State: TX
Odometer Status: READABLE
Odometer Reading: 258910
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707066
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 11:10:34 AM
Test End Date/Time: Thursday, May 01,
2014 11:11:44 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3600
VIN: 1HVBBABL5TH417825
License Plate: 1057106
LP State: TX
Odometer Status: READABLE
Odometer Reading: 224641
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707067
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 11:13:57 AM
Test End Date/Time: Thursday, May 01,
2014 11:15:09 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G35707068
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3800
VIN: 1HVBBABL1TH417823
License Plate: 1057105
LP State: TX
Odometer Status: READABLE
Odometer Reading: 253749
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, March 17,
2014 11:52:59 AM
Test End Date/Time: Monday, March 17,
2014 12:01:32 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: IHC
Model: CARPENTAR
VIN: 1HVBBABL9TH417827
License Plate: 1057072
LP State: TX
Odometer Status: READABLE
Odometer Reading: 222185
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943022
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, June 03,
2014 3:12:03 AM
Test End Date/Time: Tuesday, June 03,
2014 3:20:12 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G35707091
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 1996
Make: INTERNATIO
Model: 3700
VIN: 1HVBBABL3TH417824
License Plate: 1057182
LP State: TX
Odometer Status: READABLE
Odometer Reading: 248113
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
30, 2014 8:49:19 AM
Test End Date/Time: Thursday, January
30, 2014 8:52:14 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS
Model: MVP
VIN: 1T7HT4B29X1070135
License Plate: 755657
LP State: TX
Odometer Status: READABLE
Odometer Reading: 194606
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942988
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T055

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, April 21,
2014 11:47:58 AM
Test End Date/Time: Monday, April 21,
2014 11:50:10 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBRA1N11A911795
License Plate: 807885
LP State: TX
Odometer Status: READABLE
Odometer Reading: 178490
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943047
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, January 24,
2014 10:52:56 AM
Test End Date/Time: Friday, January 24,
2014 10:55:31 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G30942978
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS MVP
Model: THOMAS
VIN: 1T7HT4B21X1070128
License Plate: 755652
LP State: TX
Odometer Status: READABLE
Odometer Reading: 213310
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, February 11, 2014 1:51:14 PM
Test End Date/Time: Tuesday, February 11, 2014 1:56:19 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: MPV
Model: THOMAS
VIN: 1T7HT4B24X1070141
License Plate: 106513
LP State: TX
Odometer Status: READABLE
Odometer Reading: 221612
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943000
Certificate Type: ONE YEAR SAFETY ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T059

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April
30, 2014 1:09:55 AM
Test End Date/Time: Wednesday, April
30, 2014 1:14:48 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBABN11A911800
License Plate: 807890
LP State: TX
Odometer Status: READABLE
Odometer Reading: 175429
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707056
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, February
04, 2014 7:52:19 AM
Test End Date/Time: Tuesday, February
04, 2014 7:54:30 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS MVP
Model: THOMAS
VIN: 1T7HT4B26X1070142
License Plate: 756100
LP State: TX
Odometer Status: READABLE
Odometer Reading: 195315
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942995
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 11:18:12 AM
Test End Date/Time: Thursday, May 01,
2014 11:19:31 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIO
Model: AMTRAN
VIN: 1HVBABR61A911723
License Plate: 1057052
LP State: TX
Odometer Status: READABLE
Odometer Reading: 213168
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707069
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, March
04, 2014 12:17:23 PM

Test End Date/Time: Tuesday, March 04,
2014 12:24:08 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30943016
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIO
Model: 1853 FC
VIN: 1HVBJABR41A911719
License Plate: 1065019
LP State: TX
Odometer Status: READABLE
Odometer Reading: 156071
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, May
21, 2014 9:44:25 PM
Test End Date/Time: Wednesday, May
21, 2014 9:46:34 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: CARL PATTON

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS MVP
Model: THOMAS
VIN: 1T7HT4B2XX1070127
License Plate: 756101
LP State: TX
Odometer Status: READABLE
Odometer Reading: 212197
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707078
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, March 28,
2014 9:21:45 AM
Test End Date/Time: Friday, March 28,
2014 9:24:05 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIO
Model: AMTRAN
VIN: 1HVBJABR71A911715
License Plate: 1037558
LP State: TX
Odometer Status: READABLE
Odometer Reading: 179512
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943034
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
30, 2014 8:37:59 AM
Test End Date/Time: Thursday, January
30, 2014 8:40:48 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBABRX1A911725
License Plate: 1057046
LP State: TX
Odometer Status: READABLE
Odometer Reading: 190842
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942987
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, March
04, 2014 1:10:58 PM

Test End Date/Time: Tuesday, March 04,
2014 1:15:46 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR
POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30943017

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 1999

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B2XX1070130

License Plate: 1057054

LP State: TX

Odometer Status: READABLE

Odometer Reading: 217439

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, April 28,
2014 5:25:39 AM
Test End Date/Time: Monday, April 28,
2014 5:28:38 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBABR81A911724
License Plate: 220847
LP State: TX
Odometer Status: READABLE
Odometer Reading: 205851
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943050
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, February
25, 2014 1:03:14 PM
Test End Date/Time: Tuesday, February
25, 2014 1:06:04 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS MVP
Model: THOMAS
VIN: 1T7HT4B23X1070132
License Plate: 756103
LP State: TX
Odometer Status: READABLE
Odometer Reading: 187364
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943005
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, March 28,
2014 11:12:37 AM
Test End Date/Time: Friday, March 28,
2014 11:13:40 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: THOMAS
Model: MVP
VIN: 1T7HT4B24X1070138
License Plate: 756098
LP State: TX
Odometer Status: READABLE
Odometer Reading: 229526
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943037
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January 23, 2014 1:43:44 PM
Test End Date/Time: Thursday, January 23, 2014 1:47:16 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: IHC 3800
Model: BLUE BIRD
VIN: 1HVBBABL4XH684962
License Plate: 756617
LP State: TX
Odometer Status: READABLE
Odometer Reading: 215601
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942976
Certificate Type: ONE YEAR SAFETY ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T072

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Monday, April 21,
2014 10:09:50 AM
Test End Date/Time: Monday, April 21,
2014 10:11:22 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: IHC
Model: 3800
VIN: 1HVBBABL8XH684964
License Plate: 756618
LP State: TX
Odometer Status: READABLE
Odometer Reading: 183419
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943045
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T073

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, May 05,
2014 10:17:15 AM
Test End Date/Time: Monday, May 05,
2014 10:19:30 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: INTERNATIO
Model: 3800
VIN: 1HVBBABLXXH684965
License Plate: 756619
LP State: TX
Odometer Status: READABLE
Odometer Reading: 180152
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707071
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, July 24,
2014 6:38:40 AM
Test End Date/Time: Thursday, July 24,
2014 6:41:16 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIO
Model: AMTRAN
VIN: 1HVBRA91A911817
License Plate: 812317
LP State: TX
Odometer Status: READABLE
Odometer Reading: 198005
Corrected Odometer:
Insurance Expiration: 07/01/2015
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707129
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
30, 2014 8:16:12 AM
Test End Date/Time: Thursday, January
30, 2014 8:20:52 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: INTERNATIO
Model: 3700
VIN: 1HVBBABL1XH684966
License Plate: 1091318
LP State: TX
Odometer Status: READABLE
Odometer Reading: 185943
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942986
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T077

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 10:15:24 AM
Test End Date/Time: Thursday, May 01,
2014 10:16:43 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBABR51A911714
License Plate: 805610
LP State: TX
Odometer Status: READABLE
Odometer Reading: 168822
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707064
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T078

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, April 21,
2014 10:24:03 AM
Test End Date/Time: Monday, April 21,
2014 10:25:51 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIONAL
Model: AMTRAN
VIN: 1HVBABR91A911716
License Plate: 1057256
LP State: TX
Odometer Status: READABLE
Odometer Reading: 182231
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943046
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T079

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November
15, 2013 7:13:56 PM
Test End Date/Time: Friday, November
15, 2013 7:15:15 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: IHC
Model: BLUEBIRD
VIN: 1HVBBABL3XH684970
License Plate: 756624
LP State: TX
Odometer Status: READABLE
Odometer Reading: 186229
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942942
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Wednesday, June 25, 2014 1:02:15 AM
Test End Date/Time: Wednesday, June 25, 2014 1:04:22 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBRABL31A911814
License Plate: 810482
LP State: TX
Odometer Status: READABLE
Odometer Reading: 203274
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707094
Certificate Type: ONE YEAR SAFETY ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T081

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, March
05, 2014 11:50:32 AM
Test End Date/Time: Wednesday, March
05, 2014 11:53:43 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30943018
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IC
Model: AMTRAN
VIN: 1HVBJABR31A911727
License Plate: 1065173
LP State: TX
Odometer Status: READABLE
Odometer Reading: 139797
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, March
19, 2014 11:23:00 AM
Test End Date/Time: Wednesday, March
19, 2014 11:25:47 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAM
VIN: 1HVBABR71A911729
License Plate: 1057257
LP State: TX
Odometer Status: READABLE
Odometer Reading: 173940
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943024
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Wednesday, March
19, 2014 11:27:25 AM
Test End Date/Time: Wednesday, March
19, 2014 11:30:36 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIO
Model: 1853 FC
VIN: 1HVBJABR51A911731
License Plate: 1057183
LP State: TX
Odometer Status: READABLE
Odometer Reading: 207157
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943025
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T084

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November
22, 2013 8:24:11 PM
Test End Date/Time: Friday, November
22, 2013 8:26:29 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: INTERNATIONAL
Model: BLUEBIRD
VIN: 1HVBBABL3XH684967
License Plate: 756621
LP State: TX
Odometer Status: READABLE
Odometer Reading: 194756
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942951
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T087

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
November 19, 2013 7:21:56 PM
Test End Date/Time: Tuesday, November
19, 2013 7:24:39 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR
POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Inspection Information

Certificate #: G30942946
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus
Year: 1999
Make: B & L
Model: UTILITY
VIN: 1HVBBABL5XH684968
License Plate: 756622
LP State: TX
Odometer Status: READABLE
Odometer Reading: 200635
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 11:22:07 AM

Test End Date/Time: Thursday, May 01,
2014 11:23:28 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 9600

VIN: 1HVBRABN31A911801

License Plate: 807891

LP State: TX

Odometer Status: READABLE

Odometer Reading: 185931

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707070

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T-089

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, May 20,
2014 11:37:11 AM

Test End Date/Time: Tuesday, May 20,
2014 11:39:43 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: AMTRAN

VIN: 1HVBRA71A911798

License Plate: 807888

LP State: TX

Odometer Status: READABLE

Odometer Reading: 184743

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707075

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, May 20,
2014 11:59:11 AM

Test End Date/Time: Tuesday, May 20,
2014 12:02:36 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 9600

VIN: 1HVBRABN91A911799

License Plate: 807889

LP State: TX

Odometer Status: READABLE

Odometer Reading: 127497

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707076

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, July 25,
2014 6:26:42 AM

Test End Date/Time: Friday, July 25, 2014
6:28:39 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G35707131

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: AMTRAN

VIN: 1HVBRABL81A911811

License Plate: 810481

LP State: TX

Odometer Status: READABLE

Odometer Reading: 182409

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, April 29,
2014 7:08:53 AM

Test End Date/Time: Tuesday, April 29,
2014 7:11:44 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: AMTRAN

VIN: 1HVBjabr21A911721

License Plate: 805608

LP State: TX

Odometer Status: READABLE

Odometer Reading: 223220

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707053

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, February 03, 2014 2:02:44 PM

Test End Date/Time: Monday, February 03, 2014 2:05:08 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus

Year: 2004

Make: IHC

Model: AMTRAN

VIN: 4DRBRAAN14B971741

License Plate: 870816

LP State: TX

Odometer Status: READABLE

Odometer Reading: 160999

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942993

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Tuesday, April 15,
2014 10:39:22 PM
Test End Date/Time: Tuesday, April 15,
2014 10:41:54 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MARCONY RUIZ

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIO
Model: 1853 FC
VIN: 1HVBJABR51A911728
License Plate: 804905
LP State: TX
Odometer Status: READABLE
Odometer Reading: 165568
Corrected Odometer:
Insurance Expiration: 07/01/2015
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943044
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April
02, 2014 8:02:53 AM

Test End Date/Time: Wednesday, April
02, 2014 8:08:18 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: AMTRAN

VIN: 1HVBjabr01A911717

License Plate: 1091297

LP State: TX

Odometer Status: READABLE

Odometer Reading: 225632

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943042

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

BUS STATE INSPECTION REPORT


Bus #: T-1000

Tech #: M.R. 1126

Date: 8-20-2013

Time: 9:46 AM

Previous State Inspection #: 621189701

New State Inspection Cert #: 
G26891173

Year: 2005

Make: IHC

Model: AMTRAN

Vin #: 4DRBUAAN65B979124

Lic-plate #: 109-1374

Mileage: 159449

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
September 06, 2012 9:10:26 AM
Test End Date/Time: Thursday,
September 06, 2012 9:22:48 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus
Year: 2005
Make: IC
Model: PB10500
VIN: 4DRBUAANX5B979126
License Plate: 227217
LP State: TX
Odometer Status: READABLE
Odometer Reading: 110279
Corrected Odometer:
Insurance Expiration: 07/01/2013
Insurance Mileage Expiration:

Inspection Information

Certificate #: G21189711
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Wednesday,
September 05, 2012 4:09:13 PM
Test End Date/Time: Wednesday,
September 05, 2012 4:13:55 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus
Year: 2005
Make: IHC
Model: AMTRAM
VIN: 4DRBUAAN85B979125
License Plate: 1018348
LP State: TX
Odometer Status: READABLE
Odometer Reading: 144870
Corrected Odometer:
Insurance Expiration: 07/01/2013
Insurance Mileage Expiration:

Inspection Information

Certificate #: G21189707
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T-1002

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Wednesday,
September 05, 2012 4:15:02 PM
Test End Date/Time: Wednesday,
September 05, 2012 4:19:14 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus
Year: 2005
Make: IHC
Model: AMTRAN
VIN: 4DRBUAAN35B979128
License Plate: 1057144
LP State: TX
Odometer Status: READABLE
Odometer Reading: 134586
Corrected Odometer:
Insurance Expiration: 07/01/2013
Insurance Mileage Expiration:

Inspection Information

Certificate #: G21189709
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

BUS STATE INSPECTION REPORT

Bus #: 71004

Tech #: Rayonha

Date: 08-7-13

Time: 11 45

Previous State Inspection #: 09-03

New State Inspection Cert #: 8-4



Year: 2005

Make: IHC

Model: Amtran

Vin #: 4DRBUAAN15B979127

Lic-plate #: 880-288

Mileage: 164186

BUS STATE INSPECTION REPORT

Bus #: T1005

Tech #: Jayantha

Date: 07-12-13

Time: 12.00 Pm

Previous State Inspection #: 7-3



G26891139

New State Inspection Cert #: 7-4

Year: 2006

Make: IHC

Model: AMTRN

Vin #: 4DRBUAAN16B248067

Lic-plate #: 899-931

Mileage: 137317

BUS STATE INSPECTION REPORT


Bus #: T-1006

Tech #: DAVE RASZYNSKI

Date: 7-9-2013

Time: 5:35 PM

Previous State Inspection #: WA

New State Inspection Cert #: 
G26891132

Year: 2006

Make: INTERNATIONAL

Model: AMTRAN

Vin #: 4DRBUAAN36B248068

Lic-plate #: 899-932

Mileage: 118187

BUS STATE INSPECTION REPORT

Bus #: T-1007

Tech #: 1132

Date: 5/31/13

Time: 1:15 p.m.

Previous State Inspection #: G-16856136

New State Inspection Cert #: _____



Year: 2007

Make: IHC

Model: Amtran

Vin #: 4DRBUAAN57B346616

Lic-plate #: 221504

Mileage: 101663

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Monday, October 28, 2013 2:38:00 PM
Test End Date/Time: Monday, October 28, 2013 2:40:58 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2007
Make: INTERNATIO
Model: AMTRAN
VIN: 4DRBUAAN57B346617
License Plate: 221507
LP State: TX
Odometer Status: READABLE
Odometer Reading: 123437
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942911
Certificate Type: ONE YEAR SAFETY ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

BUS STATE INSPECTION REPORT

Bus #: 7-1009

Tech #: DANE KASZYNSKI

Date: 5-15-2013

Time: 7:55 PM

Previous State Inspection #: G16856127

New State Inspection Cert #:



G26891088

Year: 2007

Make: INTERNATIONAL

Model: AMTRAN

Vin #: 4DRBUAAN 77B346618

Lic-plate #: 221-508

Mileage: 119 965

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, April 18,
2013 3:09:47 PM

Test End Date/Time: Thursday, April 18,
2013 3:14:21 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CHRIS CHADDICK

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: AMTRAN

VIN: 1HVBABR21A911718

License Plate: 804901

LP State: TX

Odometer Status: READABLE

Odometer Reading: 188279

Corrected Odometer:

Insurance Expiration: 07/01/2013

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891069

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, October
22, 2013 9:11:23 PM

Test End Date/Time: Tuesday, October
22, 2013 9:17:39 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2007

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBUAAN97B346619

License Plate: 221509

LP State: TX

Odometer Status: READABLE

Odometer Reading: 119292

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942908

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
November 14, 2013 4:57:38 AM

Test End Date/Time: Thursday, November
14, 2013 5:02:34 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Vehicle Type: School Bus

Year: 2007

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBUAAN57B346620

License Plate: 221511

LP State: TX

Odometer Status: READABLE

Odometer Reading: 117869

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942935

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
November 13, 2013 8:41:51 PM
Test End Date/Time: Wednesday,
November 13, 2013 8:43:55 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2007
Make: INTERNATIONAL
Model: AMTRAN
VIN: 4DRBUAAN77B346621
License Plate: 221512
LP State: TX
Odometer Status: READABLE
Odometer Reading: 113364
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942934
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
November 21, 2013 7:30:48 PM

Test End Date/Time: Thursday, November
21, 2013 7:32:45 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Inspection Information

Certificate #: G30942949

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 2007

Make: IC CORPORATION

Model: PB 10500

VIN: 4DRBUAAN97B346622

License Plate: 221513

LP State: TX

Odometer Status: READABLE

Odometer Reading: 131883

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November
15, 2013 1:16:11 PM

Test End Date/Time: Friday, November
15, 2013 1:18:11 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Inspection Information

Certificate #: G30942940

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2007

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBUAAN07B346623

License Plate: 221514

LP State: TX

Odometer Status: READABLE

Odometer Reading: 133228

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

BUS STATE INSPECTION REPORT

Bus #: 7-1015

Tech #: DANE KASZYNSKI

Date: 7-8-2013

Time: 7:15 PM

Previous State Inspection #: G 16856166

New State Inspection Cert #:



Year: 2008

Make: INTERNATIONAL

Model: AM TRAN

Vin #: 4DRBUAAN58B537939

Lic-plate #: 101-6066

Mileage: 97007



G26891148

BUS STATE INSPECTION REPORT

Bus #: 1016

Tech #: P Vincent

Date: 7/30/13

Time: 11:40 am

Previous State Inspection #: G16856189

New State Inspection Cert #: G26891148

Year: 2008

Make: IHC

Model: Amtran

Vin #: 4DRBUAAN18B537940

Lic-plate #: 1016067

Mileage: 99619

BUS STATE INSPECTION REPORT

Bus #: T1017

Tech #: Jayantha

Date: 06-26-13

Time: 16:15

Previous State Inspection #: 6-3

New State Inspection Cert #: 6-4



Year: 2008

Make: IHC

Model: Amtran.

Vin #: 4DRBUAAN38B537941

Lic-plate #: 101-6068

Mileage: 104895

BUS STATE INSPECTION REPORT

Bus #: 1018

Tech #: 1134

Date: 5/20/13

Time: _____

Previous State Inspection #: _____

New State Inspection Cert #: _____



Year: 2008

Make: IMC

Model: Amtron

Vin #: UDR3VA4NS8B337942

Lic-plate #: 101606G

Mileage: 48752

BUS STATE INSPECTION REPORT

Bus #: 7-1019

Tech #: DAVE KASZYNSKI

Date: 6-4-2013

Time: 5:05 PM

Previous State Inspection #: G16856151

New State Inspection Cert #:



Year: 2008

Make: INTERNATIONAL

Model: AM TRON

Vin #: 4DRBUAAN38B537938

Lic-plate #: 101-6065

Mileage: 74274

BUS STATE INSPECTION REPORT


Bus #: T-1020

Tech #: 1142

Date: 8-8-13

Time: 5:30 pm

Previous State Inspection #: G16856195

New State Inspection Cert #:  G26891161

Year: 2008

Make: IHC

Model: AMTRAN

Vin #: 4DR3URAN78B537943

Lic-plate #: 108-8282

Mileage: 79,288

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
September 23, 2013 7:46:15 PM

Test End Date/Time: Monday, September
23, 2013 7:53:53 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G26891188

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBUAAN19B042980

License Plate: 1018371

LP State: TX

Odometer Status: READABLE

Odometer Reading: 98477

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, March 19,
2013 3:19:08 PM

Overall Result: Pass

Test End Date/Time: Tuesday, March 19,
2013 3:22:27 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2009

Make: INTERNATIO

Model: CE300

VIN: 4DRBUAAN39B042981

License Plate: 1018372

LP State: TX

Odometer Status: READABLE

Odometer Reading: 92760

Corrected Odometer:

Insurance Expiration: 07/01/2013

Insurance Mileage Expiration:

Inspection Information

Certificate #: G21189842

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, February
18, 2013 4:13:09 PM

Test End Date/Time: Monday, February
18, 2013 4:20:21 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: IHC

Model: PB-10500

VIN: 4DRBUAAN59B042982

License Plate: 1018339

LP State: TX

Odometer Status: READABLE

Odometer Reading: 58389

Corrected Odometer:

Insurance Expiration: 07/01/2013

Insurance Mileage Expiration:

Inspection Information

Certificate #: G21189818

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
September 18, 2013 4:50:14 PM
Test End Date/Time: Wednesday,
September 18, 2013 4:52:35 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2009
Make: IHC
Model: INTERNATIONAL
VIN: 4DRBUAAN79B042983
License Plate: 1018373
LP State: TX
Odometer Status: READABLE
Odometer Reading: 77451
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891181
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Thursday,
September 12, 2013 7:10:22 PM
Test End Date/Time: Thursday,
September 12, 2013 7:14:17 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2009
Make: IC
Model: PB10500
VIN: 4DRBUAAN99B042984
License Plate: 1018374
LP State: TX
Odometer Status: READABLE
Odometer Reading: 90554
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891179
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T-1025

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, March
13, 2014 8:38:05 AM

Test End Date/Time: Thursday, March 13,
2014 8:39:40 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: IHC-PB10500

Model: PB10500

VIN: 4DRBUAAN09B042985

License Plate: 1018340

LP State: TX

Odometer Status: READABLE

Odometer Reading: 103816

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943020

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, July
23, 2014 9:44:49 AM

Test End Date/Time: Wednesday, July 23,
2014 9:47:20 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2009

Make: IHC

Model: PB10500

VIN: 4DRBUAAN29B042986

License Plate: 1037425

LP State: TX

Odometer Status: READABLE

Odometer Reading: 114103

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707128

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
23, 2014 1:32:07 PM

Test End Date/Time: Thursday, January
23, 2014 1:34:50 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: IC

Model: PB10500

VIN: 4DRBUAAN49B042987

License Plate: 1018341

LP State: TX

Odometer Status: READABLE

Odometer Reading: 86207

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942975

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
February 26, 2014 10:35:12 AM
Test End Date/Time: Wednesday,
February 26, 2014 10:37:26 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2009
Make: IHC
Model: PB-10500
VIN: 4DRBUAAN69B042988
License Plate: 1018329
LP State: TX
Odometer Status: READABLE
Odometer Reading: 71536
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943006
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
February 26, 2014 10:44:35 AM
Test End Date/Time: Wednesday,
February 26, 2014 10:47:12 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2009
Make: IHC
Model: PB10500
VIN: 4DRBUAAN89B042989
License Plate: 1018330
LP State: TX
Odometer Status: READABLE
Odometer Reading: 93089
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943007
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
December 03, 2013 6:27:05 PM

Test End Date/Time: Tuesday, December
03, 2013 6:28:52 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2009

Make: IHC

Model: IHC

VIN: 4DRBUAAN49B042990

License Plate: 1018331

LP State: TX

Odometer Status: READABLE

Odometer Reading: 85461

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942955

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
September 19, 2013 2:05:08 PM
Test End Date/Time: Thursday,
September 19, 2013 2:10:30 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2009
Make: IHC
Model: PB10500
VIN: 4DRBUAAN69B042991
License Plate: 1018332
LP State: TX
Odometer Status: READABLE
Odometer Reading: 93204
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891183
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April
30, 2014 11:26:04 AM

Test End Date/Time: Wednesday, April
30, 2014 11:30:20 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: IHC

Model: PB10500

VIN: 4DRBUAAN89B042992

License Plate: 1018333

LP State: TX

Odometer Status: READABLE

Odometer Reading: 104783

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G37507061

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
September 23, 2013 8:28:58 PM

Overall Result: Pass

Test End Date/Time: Monday, September
23, 2013 8:34:09 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus

Year: 2009

Make: IHC

Model: MAXXFORCE

VIN: 4DRBUAAN3AB211286

License Plate: 1057271

LP State: TX

Odometer Status: READABLE

Odometer Reading: 70372

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891190

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
September 24, 2013 7:24:46 PM

Overall Result: Pass

Test End Date/Time: Tuesday, September
24, 2013 7:28:34 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: IHC

VIN: 4DRBUAAN9AB211289

License Plate: 1057121

LP State: TX

Odometer Status: READABLE

Odometer Reading: 7964

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891194

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
September 25, 2013 7:15:38 PM
Test End Date/Time: Wednesday,
September 25, 2013 7:19:39 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2010
Make: INTERNATIO
Model: PB10500
VIN: 4DRBUAAN5AB211287
License Plate: 1057122
LP State: TX
Odometer Status: READABLE
Odometer Reading: 77151
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891195
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, October 22, 2013 6:45:46 PM

Test End Date/Time: Tuesday, October 22, 2013 6:49:44 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: INTERNATIO

Model: M-1400

VIN: 4DRBUAAN6AB211296

License Plate: 1057123

LP State: TX

Odometer Status: READABLE

Odometer Reading: 101113

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942907

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Tuesday, October 29, 2013 8:31:33 PM
Test End Date/Time: Tuesday, October 29, 2013 8:33:36 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2010
Make: IHC
Model: C3402
VIN: 4DRBUAAN4AB211295
License Plate: 1057124
LP State: TX
Odometer Status: READABLE
Odometer Reading: 74361
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942916
Certificate Type: ONE YEAR SAFETY ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, October
28, 2013 8:40:10 PM

Test End Date/Time: Monday, October
28, 2013 8:42:31 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: INTERNATIONAL

VIN: 4DRBUAAN5AB211290

License Plate: 1057125

LP State: TX

Odometer Status: READABLE

Odometer Reading: 67283

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942912

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Thursday, April 25,
2013 7:38:57 AM

Test End Date/Time: Thursday, April 25,
2013 7:41:49 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: CHRIS CHADDICK

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: IHC
Model: AMTRAN
VIN: 1HVBABR41A911722
License Plate: 804902
LP State: TX
Odometer Status: READABLE
Odometer Reading: 149953
Corrected Odometer:
Insurance Expiration: 07/01/2013
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891076
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Thursday, October 31, 2013 8:28:14 PM
Test End Date/Time: Thursday, October 31, 2013 8:29:53 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2010
Make: IHC
Model: INTERNATIONAL
VIN: 4DRBUAAN9AB211292
License Plate: 1057156
LP State: TX
Odometer Status: READABLE
Odometer Reading: 70753
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942925
Certificate Type: ONE YEAR SAFETY ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Wednesday,
October 30, 2013 9:21:42 PM
Test End Date/Time: Wednesday,
October 30, 2013 9:24:10 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus
Year: 2010
Make: INTERNATIO
Model: C3402
VIN: 4DRBUAAN1AB211285
License Plate: 1057127
LP State: TX
Odometer Status: READABLE
Odometer Reading: 88087
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942918
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T-1041

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Monday, December
02, 2013 6:49:25 PM
Test End Date/Time: Monday, December
02, 2013 6:51:02 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus
Year: 2010
Make: INTERNATIO
Model: C3402
VIN: 4DRBUAAN8AB211297
License Plate: 1057128
LP State: TX
Odometer Status: READABLE
Odometer Reading: 75483
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942953
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T-1042

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Thursday,
November 14, 2013 7:39:20 PM

Overall Result: Pass

Test End Date/Time: Thursday, November
14, 2013 7:42:58 PM

Vehicle Information

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus
Year: 2010
Make: INTERNATIO
Model: C3402
VIN: 4DRBUAANXAB211298
License Plate: 1057129
LP State: TX
Odometer Status: READABLE
Odometer Reading: 69454
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942938
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, February
13, 2014 1:35:23 PM

Test End Date/Time: Thursday, February
13, 2014 1:38:53 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: INTERNATIONAL

VIN: 4DRBUAAN7AB211288

License Plate: 1057130

LP State: TX

Odometer Status: READABLE

Odometer Reading: 87357

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943002

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, February
27, 2014 1:00:14 PM

Overall Result: Pass

Test End Date/Time: Thursday, February
27, 2014 1:01:22 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: INTERNATIONAL

VIN: 4DRBUAAN7AB211291

License Plate: 1057131

LP State: TX

Odometer Status: READABLE

Odometer Reading: 76613

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943013

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, March 28,
2014 10:54:06 AM

Test End Date/Time: Friday, March 28,
2014 10:55:34 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: C3402

VIN: 4DRBUAAN0AB211293

License Plate: 1057132

LP State: TX

Odometer Status: READABLE

Odometer Reading: 69761

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943036

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 15,
2014 12:28:26 AM

Test End Date/Time: Thursday, May 15,
2014 12:32:50 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DONNIE BILLMEIER

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: INTERNATIO

Model: 5000 SFA

VIN: 4DRBUAAN2AB211294

License Plate: 1057133

LP State: TX

Odometer Status: READABLE

Odometer Reading: 89570

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707074

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
September 26, 2013 9:20:14 PM
Test End Date/Time: Thursday,
September 26, 2013 9:23:31 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2011
Make: IHC
Model: CE
VIN: 4DRBUAAN2BB356823
License Plate: 1057262
LP State: TX
Odometer Status: READABLE
Odometer Reading: 61648
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891198
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, November
18, 2013 11:56:02 AM

Test End Date/Time: Monday, November
18, 2013 11:59:43 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DONNIE BILLMEIER

Vehicle Information

Vehicle Type: School Bus
Year: 2011
Make: INTERNATIONAL
Model: CE
VIN: 4DRBUAAN4BB356824
License Plate: 1057263
LP State: TX
Odometer Status: READABLE
Odometer Reading: 51168
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942943
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
December 18, 2013 10:27:02 AM
Test End Date/Time: Wednesday,
December 18, 2013 10:28:53 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2011
Make: INTERNATIO
Model: CE300
VIN: 4DRBUAAN3BB356829
License Plate: 1057264
LP State: TX
Odometer Status: READABLE
Odometer Reading: 43936
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942964
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, January 31,
2014 6:41:10 AM

Test End Date/Time: Friday, January 31,
2014 6:45:38 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2011

Make: INTERNATIONAL

Model: CE300/AMTRAN

VIN: 4DRBUAANXBB356830

License Plate: 1057265

LP State: TX

Odometer Status: READABLE

Odometer Reading: 68659

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942990

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
February 26, 2014 11:22:00 AM
Test End Date/Time: Wednesday,
February 26, 2014 11:24:52 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2011
Make: INTERNATIO
Model: PB10500
VIN: 4DRBUAAN1BB356831
License Plate: 1057266
LP State: TX
Odometer Status: READABLE
Odometer Reading: 57388
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943008
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, March
27, 2014 8:23:35 AM

Test End Date/Time: Thursday, March 27,
2014 8:27:07 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2012

Make: INTERNATIONAL

Model: CE

VIN: 4DRBUAAN3BB356832

License Plate: 1057267

LP State: TX

Odometer Status: READABLE

Odometer Reading: 56961

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943031

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, May
21, 2014 12:42:13 AM
Test End Date/Time: Wednesday, May
21, 2014 12:45:57 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DONNIE BILLMEIER

Vehicle Information

Vehicle Type: School Bus
Year: 2011
Make: IHC
Model: CE
VIN: 4DRBUAAN5BB356833
License Plate: 1057268
LP State: TX
Odometer Status: READABLE
Odometer Reading: 49367
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707077
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 2:23:18 AM

Test End Date/Time: Thursday, May 01,
2014 2:25:04 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: ERIC ALLISON

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: PB105

VIN: 4DRBUAAN8CB397460

License Plate: 1057302

LP State: TX

Odometer Status: READABLE

Odometer Reading: 62831

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707063

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, May
28, 2014 10:45:57 AM

Test End Date/Time: Wednesday, May
28, 2014 10:47:00 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G35707082

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: PB-105

VIN: 4DRBUAANXCB397458

License Plate: 1057303

LP State: TX

Odometer Status: READABLE

Odometer Reading: 51103

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 9:21:14 AM
Test End Date/Time: Monday, June 30,
2014 9:23:09 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: INTERNATIONAL
Model: PB-10500
VIN: 4DRBUAAN8CB397457
License Plate: 1057304
LP State: TX
Odometer Status: READABLE
Odometer Reading: 43062
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707112
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, July 24,
2014 6:44:03 AM

Test End Date/Time: Thursday, July 24,
2014 6:46:37 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2012

Make: AMTRAN

Model: AMTRAN

VIN: 4DRBUAANXCB397461

License Plate: 1057305

LP State: TX

Odometer Status: READABLE

Odometer Reading: 60284

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707130

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

BUS STATE INSPECTION REPORT


Bus #: T-1059

Tech #: 1142 AM

Date: 8-7-13

Time: 11:12 AM

Previous State Inspection #: G21189702

New State Inspection Cert #: 
G26891157

Year: 2012

Make: IHC

Model: PB105

Vin #: 4DRT3UAAN9CB397466

Lic-plate #: 105-7306

Mileage: 45881

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
September 25, 2013 7:58:47 PM
Test End Date/Time: Wednesday,
September 25, 2013 8:00:52 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: INTERNATIONAL
Model: AMTRAN
VIN: 4DRBUAAN6CB397456
License Plate: 1057307
LP State: TX
Odometer Status: READABLE
Odometer Reading: 39541
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891196
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, October 29, 2013 6:53:48 PM

Test End Date/Time: Tuesday, October 29, 2013 6:55:44 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: PB105

VIN: 4DRBUAAN0CB397467

License Plate: 1057308

LP State: TX

Odometer Status: READABLE

Odometer Reading: 49326

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942915

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
November 14, 2013 5:51:59 PM

Test End Date/Time: Thursday, November
14, 2013 5:53:45 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30942937

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2012

Make: INTERNATIONAL

Model: PB105

VIN: 4DRBUAAN7CB397465

License Plate: 1057309

LP State: TX

Odometer Status: READABLE

Odometer Reading: 49991

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Friday, January 24,
2014 10:40:15 AM
Test End Date/Time: Friday, January 24,
2014 10:43:52 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus
Year: 2012
Make: IHC
Model: CE
VIN: 4DRBUAAN3CB456074
License Plate: 1057310
LP State: TX
Odometer Status: READABLE
Odometer Reading: 54246
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942977
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T-1063

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, May
28, 2014 11:06:07 AM

Test End Date/Time: Wednesday, May
28, 2014 11:07:15 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2012

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBUAAN8CB456068

License Plate: 1057311

LP State: TX

Odometer Status: READABLE

Odometer Reading: 83839

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707083

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 29,
2014 4:31:38 AM

Test End Date/Time: Thursday, May 29,
2014 4:48:43 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MAX MONDRAGON

Vehicle Type: School Bus

Year: 2012

Make: IC

Model: PB-10500

VIN: 4DRBUAAN0CB456064

License Plate: 1057312

LP State: TX

Odometer Status: READABLE

Odometer Reading: 50578

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707084

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
February 26, 2014 11:31:18 AM
Test End Date/Time: Wednesday,
February 26, 2014 11:33:49 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: IHC
Model: CE
VIN: 4DRBUAAN2CB456065
License Plate: 1057313
LP State: TX
Odometer Status: READABLE
Odometer Reading: 42484
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943009
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 9:13:30 AM

Test End Date/Time: Monday, June 30,
2014 9:16:14 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2012

Make: INTERNATIONAL

Model: CE

VIN: 4DRBUAAN4CB456066

License Plate: 1057314

LP State: TX

Odometer Status: READABLE

Odometer Reading: 54112

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707111

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, October 01, 2013 5:09:23 AM

Test End Date/Time: Tuesday, October 01, 2013 5:10:43 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: ERIC ALLISON

Vehicle Type: School Bus

Year: 2012

Make: INTERNATIONAL

Model: CE

VIN: 4DRBUAAN6CB456067

License Plate: 1057315

LP State: TX

Odometer Status: READABLE

Odometer Reading: 31736

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942904

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, September 27, 2013 9:18:09 AM

Test End Date/Time: Friday, September 27, 2013 9:21:57 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CARL PATTON

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: INTERNATIONAL

VIN: 4DRBUAANXCB456069

License Plate: 1057316

LP State: TX

Odometer Status: READABLE

Odometer Reading: 48550

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891191

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April
30, 2014 2:34:09 AM
Test End Date/Time: Wednesday, April
30, 2014 2:36:28 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: CARL PATTON

Vehicle Information

Vehicle Type: School Bus
Year: 2001
Make: INTERNATIO
Model: 1853 FC
VIN: 1HVBABR31A911730
License Plate: 805607
LP State: TX
Odometer Status: READABLE
Odometer Reading: 196279
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707057
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Wednesday,
October 30, 2013 8:44:00 PM
Test End Date/Time: Wednesday,
October 30, 2013 8:48:49 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: IHC
Model: INTERNATIONAL
VIN: 4DRBUAAN6CB456070
License Plate: 1057317
LP State: TX
Odometer Status: READABLE
Odometer Reading: 47160
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942917
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October
31, 2013 9:19:07 PM

Test End Date/Time: Thursday, October
31, 2013 9:23:21 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2012

Make: INTERNATIONAL

Model: CE

VIN: 4DRBUAAN8CB456071

License Plate: 1057318

LP State: TX

Odometer Status: READABLE

Odometer Reading: 31297

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942926

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
November 20, 2013 4:08:15 PM
Test End Date/Time: Wednesday,
November 20, 2013 4:10:03 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: IHC
Model: CE
VIN: 4DRBUAANXCB456072
License Plate: 1057319
LP State: TX
Odometer Status: READABLE
Odometer Reading: 39719
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942947
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

1-1072

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
November 20, 2013 7:09:15 PM

Test End Date/Time: Wednesday,
November 20, 2013 7:13:59 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: CE

VIN: 4DRBUAAN1CB456073

License Plate: 1057320

LP State: TX

Odometer Status: READABLE

Odometer Reading: 40642

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942948

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, January 31,
2014 12:52:21 PM

Overall Result: Pass

Test End Date/Time: Friday, January 31,
2014 12:54:41 PM

Vehicle Information

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus
Year: 2012
Make: INTERNATIONAL
Model: CE
VIN: 4DRBUAAN2CB456017
License Plate: 1057321
LP State: TX
Odometer Status: READABLE
Odometer Reading: 51357
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942991
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, January 31,
2014 12:56:36 PM

Test End Date/Time: Friday, January 31,
2014 12:58:11 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: CE

VIN: 4DRBUAAN4CB456018

License Plate: 1057322

LP State: TX

Odometer Status: READABLE

Odometer Reading: 45863

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942992

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T 1075

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, March 28,
2014 8:28:47 AM

Test End Date/Time: Friday, March 28,
2014 8:59:04 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2013
Make: IC
Model: CE
VIN: 4DRBUAAN1DB324027
License Plate: 1065150
LP State: TX
Odometer Status: READABLE
Odometer Reading: 25963
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943033
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T1076

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, March
20, 2013 5:35:33 PM

Test End Date/Time: Wednesday, March
20, 2013 5:43:34 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G21189845

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2012

Make: IC

Model: INTERNATIONAL

VIN: 4DRBUAAN3DB324028

License Plate: 1065151

LP State: TX

Odometer Status: READABLE

Odometer Reading: 9728

Corrected Odometer:

Insurance Expiration: 07/01/2013

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T1077

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November 01, 2013 8:51:00 PM

Test End Date/Time: Friday, November 01, 2013 8:58:47 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus

Year: 2013

Make: IHC

Model: CE MAXFORCE

VIN: 4DRBUAAN7DB324033

License Plate: 1065157

LP State: TX

Odometer Status: READABLE

Odometer Reading: 17177

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942928

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

11078

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, March 31,
2014 11:51:50 AM

Test End Date/Time: Monday, March 31,
2014 11:57:02 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2013

Make: IHC

Model: CE

VIN: 4DRBUAAN3DB324031

License Plate: 1065153

LP State: TX

Odometer Status: READABLE

Odometer Reading: 26704

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943041

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T1079

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October 31, 2013 8:18:14 PM

Test End Date/Time: Thursday, October 31, 2013 8:22:21 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2013

Make: IC

Model: CE

VIN: 4DRBUAAN5DB324032

License Plate: 1065154

LP State: TX

Odometer Status: READABLE

Odometer Reading: 17556

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942924

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T1080

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April
30, 2014 11:21:48 AM
Test End Date/Time: Wednesday, April
30, 2014 11:23:42 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2013
Make: IC
Model: MAXFORCE
VIN: 4DRBUAAN9DB324048
License Plate: 1065155
LP State: TX
Odometer Status: READABLE
Odometer Reading: 21220
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707060
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T1081

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, April 29,
2014 6:01:34 AM

Test End Date/Time: Tuesday, April 29,
2014 6:10:09 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus

Year: 2013

Make: IC

Model: MAXFORCE

VIN: 4DRBUAAN9DB324034

License Plate: 1065156

LP State: TX

Odometer Status: READABLE

Odometer Reading: 20484

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707051

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T1082

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April 30, 2014 11:09:49 AM

Test End Date/Time: Wednesday, April 30, 2014 11:11:51 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2013

Make: IC

Model: CE

VIN: 4DRBUAAN1DB324030

License Plate: 1065157

LP State: TX

Odometer Status: READABLE

Odometer Reading: 23226

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707058

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T1083

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October 31, 2013 10:22:23 AM

Test End Date/Time: Thursday, October 31, 2013 10:30:56 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus

Year: 2013

Make: IC

Model: CE

VIN: 4DRBUAAN5DB324029

License Plate: 1065161

LP State: TX

Odometer Status: READABLE

Odometer Reading: 18273

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942922

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety Vehicle Inspection Report

Test Start Date/Time: Monday, March 31,
2014 3:06:33 AM
Test End Date/Time: Monday, March 31,
2014 3:09:18 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus
Year: 2013
Make: IHC
Model: CE
VIN: 4DRBUAAN2DB324036
License Plate: 1065158
LP State: TX
Odometer Status: READABLE
Odometer Reading: 21946
Corrected Odometer:
Insurance Expiration: 07/01/2015
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943038
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T-1085

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, December
02, 2013 12:53:07 PM
Test End Date/Time: Monday, December
02, 2013 12:57:50 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus
Year: 2014
Make: IC
Model: CE
VIN: 4DRBUAAN9EB481855
License Plate: 1065197
LP State: TX
Odometer Status: READABLE
Odometer Reading: 7320
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942952
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

BUS STATE INSPECTION REPORT

Bus #: T-1087

Tech #: 114~~2~~ AM

Date: 8-23-13

Time: 5:35 pm

Previous State Inspection #: T00877267

New State Inspection Cert #: _____



Year: 2014

Make: IHC

Model: PB10500

Vin #: 4DR3UAANOEB481890

Lic-plate #: 106-5198

Mileage: 2808

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
December 11, 2013 3:37:44 PM
Test End Date/Time: Wednesday,
December 11, 2013 3:43:32 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2014
Make: IC
Model: CE
VIN: 4DRBUAAN2EB481857
License Plate: 1065199
LP State: TX
Odometer Status: READABLE
Odometer Reading: 7982
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942959
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

BUS STATE INSPECTION REPORT


Bus #: T 1089

Tech #: 1134

Date: 8/23/13

Time: 2:00

Previous State Inspection #: T COX 77280

New State Inspection Cert #:  G26891175

Year: 2014

Make: IHC

Model: P 10500

Vin #: 4DRBUAANGEB4818A3

Lic-plate #: 10A1275

Mileage: 2783

BUS STATE INSPECTION REPORT


Bus #: T-1090

Tech #: DAVE KASZYNSKI

Date: 8-12-2013

Time: 7:40 PM

Previous State Inspection #: T008 77270

New State Inspection Cert #: 
G26891165

Year: 2014

Make: International

Model: CE

Vin #: 4DRBUAAN2EB481860

Lic-plate #: 109-1276

Mileage: 3006

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
September 23, 2013 8:14:11 PM

Test End Date/Time: Monday, September
23, 2013 8:19:14 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2014

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN2EB481888

License Plate: 1091277

LP State: TX

Odometer Status: READABLE

Odometer Reading: 4730

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891189

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

BUS STATE INSPECTION REPORT

Bus #: 7-1092

Tech #: DMT Kaszynski

Date: 8-12-2013

Time: 7:15 PM

Previous State Inspection #: 7008 77273

New State Inspection Cert #:



Year: 2014

Make: International

Model: CE

Vin #: 4DRBUAAN2EB481891

Lic-plate #: 109-1278

Mileage: 2750

BUS STATE INSPECTION REPORT

Bus #: T-1093

Tech #: 1142 AM

Date: 8-15-13

Time: 8:55 AM

Previous State Inspection #: T00877274

New State Inspection Cert #:



Year: 2014

Make: IHC

Model: PB10500

Vin #: 4DR13UAA96B481886

Lic-plate #: 109-1279

Mileage: 4250

BUS STATE INSPECTION REPORT

Bus #: T-1094

Tech #: 1147 AM

Date: 8-19-13

Time: 07:48 pm

Previous State Inspection #: T00877275

New State Inspection Cert #:



Year: 2014

Make: IFC

Model: CE

Vin #: 4DRBUAAN4EB481892

Lic-plate #: 109-1280

Mileage: 3094

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
September 23, 2013 5:45:06 PM

Overall Result: Pass

Test End Date/Time: Monday, September
23, 2013 5:54:20 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2014

Make: IHC

Model: CE300

VIN: 4DRBUAANXEB481895

License Plate: 1091281

LP State: TX

Odometer Status: READABLE

Odometer Reading: 4757

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891187

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
December 17, 2013 10:02:00 AM

Overall Result: Pass

Test End Date/Time: Tuesday, December
17, 2013 10:16:56 AM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2014

Make: IC

Model: CE

VIN: 4DRBUAAN1EB481851

License Plate: 1091282

LP State: TX

Odometer Status: READABLE

Odometer Reading: 9784

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942962

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
September 18, 2013 5:53:49 PM
Test End Date/Time: Wednesday,
September 18, 2013 6:00:34 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2014
Make: IHC
Model: MAXXFORCE CE
VIN: 4DRBUAAN0EB481856
License Plate: 1091283
LP State: TX
Odometer Status: READABLE
Odometer Reading: 3759
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891182
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November
15, 2013 6:35:38 AM

Test End Date/Time: Friday, November
15, 2013 6:39:13 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus

Year: 2014

Make: IC

Model: CE

VIN: 4DRBUAAN4EB481889

License Plate: 1091284

LP State: TX

Odometer Status: READABLE

Odometer Reading: 6703

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942939

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

BUS STATE INSPECTION REPORT


Bus #: T-1099

Tech #: 1126

Date: 8-23-2013

Time: 9:50 AM

Previous State Inspection #: 008 77281

New State Inspection Cert #: 
G26891174 †

Year: 2014

Make: IHC

Model: P-10500

Vin #: 4DRBUAAN7EB481885

Lic-plate #: 109-1285

Mileage: 3410

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
December 18, 2013 2:36:34 PM
Test End Date/Time: Wednesday,
December 18, 2013 2:39:59 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2013
Make: INTL
Model: CE
VIN: 4DRBUAAN8EB481894
License Plate: 1091286
LP State: TX
Odometer Status: READABLE
Odometer Reading: 8340
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942965
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
December 10, 2013 3:33:42 PM

Overall Result: Pass

Test End Date/Time: Tuesday, December
10, 2013 3:37:09 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2013

Make: INTL

Model: CE

VIN: 4DRBUAAN3EB481852

License Plate: 1091287

LP State: TX

Odometer Status: READABLE

Odometer Reading: 8784

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942958

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, June 17,
2014 8:10:05 AM

Test End Date/Time: Tuesday, June 17,
2014 8:18:09 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus

Year: 2013

Make: INTL

Model: CE

VIN: 4DRBUAAN0EB481887

License Plate: 1091288

LP State: TX

Odometer Status: READABLE

Odometer Reading: 19120

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707103

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
September 12, 2013 5:26:19 PM
Test End Date/Time: Thursday,
September 12, 2013 5:30:35 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2013
Make: IHC
Model: CE
VIN: 4DRBUAAN1EB481896
License Plate: 1091289
LP State: TX
Odometer Status: READABLE
Odometer Reading: 3139
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891178
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday,
September 16, 2013 8:19:43 PM

Test End Date/Time: Monday, September
16, 2013 8:23:55 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Inspection Information

Certificate #: G26891180

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 2014

Make: IHC

Model: MAXXFOCE

VIN: 4DRBUAAN7EB481854

License Plate: 1091290

LP State: TX

Odometer Status: READABLE

Odometer Reading: 4207

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

T-11024

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
December 12, 2013 12:24:00 PM
Test End Date/Time: Thursday,
December 12, 2013 12:29:53 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus
Year: 2014
Make: IC
Model: CE
VIN: 4DRBUAAN5EB481898
License Plate: 1091291
LP State: TX
Odometer Status: READABLE
Odometer Reading: 6890
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942960
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
December 12, 2013 6:53:31 PM
Test End Date/Time: Thursday,
December 12, 2013 6:57:47 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2014
Make: IC
Model: CE
VIN: 4DRBUAAN6EB481859
License Plate: 1091292
LP State: TX
Odometer Status: READABLE
Odometer Reading: 8771
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942961
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
December 03, 2013 5:00:08 PM

Test End Date/Time: Tuesday, December
03, 2013 5:04:03 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G30942954

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2014

Make: IC

Model: CE

VIN: 4DRBUAAN4EB481858

License Plate: 1091293

LP State: TX

Odometer Status: READABLE

Odometer Reading: 5987

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April
17, 2013 10:47:09 AM

Test End Date/Time: Wednesday, April
17, 2013 10:48:36 AM

Overall Result: Pass

Vehicle Information

Vehicle Type: School Bus

Year: 2014

Make: IC

Model: CE

VIN: 4DRBUAAN3EB481897

License Plate:

LP State: NONE

Odometer Status: READABLE

Odometer Reading: 290

Corrected Odometer:

Insurance Expiration: 12/18/2013

Insurance Mileage Expiration:

Station Information

Station #: 1F038305

Station Name: BUS AIR MANUFACTURING

Station Address: 6630 E HWY 114

RHOME, TX 76078

Inspector Name: GEORGE HALLEY JR

Inspection Information

Certificate #: T00877292

Certificate Type:

COMMERCIAL/WINDSHIELD

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$62.00

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$62.00

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, January
14, 2014 7:39:37 AM

Test End Date/Time: Tuesday, January
14, 2014 7:44:24 AM

Overall Result: Pass

Vehicle Information

Vehicle Type: School Bus

Year: 2004

Make: IC CORP

Model: 9600

VIN: 4DRBRABN54B971823

License Plate: 868384

LP State: TX

Odometer Status: READABLE

Odometer Reading: 153312

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CHRIS CHADDICK

Inspection Information

Certificate #: G30942972

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, January 24,
2014 2:02:30 PM

Test End Date/Time: Friday, January 24,
2014 2:04:33 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2004

Make: IHC

Model: AMTRAN

VIN: 4DRBRABN14B971821

License Plate: 868382

LP State: TX

Odometer Status: READABLE

Odometer Reading: 151626

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942979

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, January
09, 2014 2:56:55 PM

Test End Date/Time: Thursday, January
09, 2014 2:59:23 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2004

Make: IC CORP

Model: AMTRAN

VIN: 4DRBRABN94B971825

License Plate: 868386

LP State: TX

Odometer Status: READABLE

Odometer Reading: 155933

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942969

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, January 24,
2014 2:59:52 PM

Test End Date/Time: Friday, January 24,
2014 3:04:08 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2004

Make: IHC

Model: AMTRAN

VIN: 4DRBRABN74B971824

License Plate: 868385

LP State: TX

Odometer Status: READABLE

Odometer Reading: 155770

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942980

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 4:17:08 AM

Test End Date/Time: Monday, June 30,
2014 4:19:10 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: AMTRAN

VIN: 1HVBRABL81A911808

License Plate: 808610

LP State: TX

Odometer Status: READABLE

Odometer Reading: 184117

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707096

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, July 25,
2014 7:12:42 AM

Test End Date/Time: Friday, July 25, 2014
7:20:21 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G35707132

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIONAL

Model: IC3S530

VIN: 1HVBRA BLX1A911809

License Plate: 1065020

LP State: TX

Odometer Status: READABLE

Odometer Reading: 189151

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, May
14, 2014 3:25:35 AM

Test End Date/Time: Wednesday, May
14, 2014 3:57:40 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 3700

VIN: 1HVBRABL51A911815

License Plate: 808612

LP State: TX

Odometer Status: READABLE

Odometer Reading: 173958

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707073

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 7:37:00 AM

Test End Date/Time: Monday, June 30,
2014 7:38:56 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G35707097

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 9600

VIN: 1HVBRA21A911822

License Plate: 812312

LP State: TX

Odometer Status: READABLE

Odometer Reading: 197366

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, June 11, 2014 10:11:11 PM

Test End Date/Time: Wednesday, June 11, 2014 10:20:27 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: PAUL VINCENT

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: IHC

Model: AMTRAN

VIN: 1HVBRA01A911818

License Plate: 1091386

LP State: TX

Odometer Status: READABLE

Odometer Reading: 175472

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707092

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T120

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, February
04, 2014 1:33:35 PM

Test End Date/Time: Tuesday, February
04, 2014 1:37:30 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2004

Make: IHC

Model: AMTRAN

VIN: 4DRBRAANX4B971740

License Plate: 870811

LP State: TX

Odometer Status: READABLE

Odometer Reading: 171196

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942996

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

7121

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, February
27, 2014 11:47:43 AM

Overall Result: Pass

Test End Date/Time: Thursday, February
27, 2014 11:49:58 AM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 2004

Make: IHC

Model: AMTRAN

VIN: 4DRBRAAN34B971739

License Plate: 870812

LP State: TX

Odometer Status: READABLE

Odometer Reading: 147041

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943011

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T122

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, February
03, 2014 2:07:26 PM

Test End Date/Time: Monday, February
03, 2014 2:11:32 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2004

Make: IHC

Model: AMTRAN

VIN: 4DRBRAAN14B971738

License Plate: 870813

LP State: TX

Odometer Status: READABLE

Odometer Reading: 167469

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942994

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T124

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, May 23,
2014 6:57:15 AM

Test End Date/Time: Friday, May 23,
2014 7:00:08 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 9600

VIN: 1HVBRA91A911820

License Plate: 808611

LP State: TX

Odometer Status: READABLE

Odometer Reading: 206958

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707079

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T127

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, May 01,
2014 10:21:19 AM

Test End Date/Time: Thursday, May 01,
2014 10:22:41 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 1853 FC

VIN: 1HVBABR91A911733

License Plate: 805611

LP State: TX

Odometer Status: READABLE

Odometer Reading: 177096

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707065

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T129

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, February 07, 2014 2:09:09 PM

Test End Date/Time: Friday, February 07, 2014 2:23:33 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2004

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBRAAN84B971736

License Plate: 870815

LP State: TX

Odometer Status: READABLE

Odometer Reading: 163380

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942999

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T135

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, May 13,
2014 12:00:22 PM

Test End Date/Time: Tuesday, May 13,
2014 12:02:28 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: IHC

Model: AMTRAN

VIN: 1HVBABR71A911732

License Plate: 805606

LP State: TX

Odometer Status: READABLE

Odometer Reading: 204864

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707072

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T136

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, July
23, 2014 4:32:12 AM

Test End Date/Time: Wednesday, July 23,
2014 4:36:37 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: IC3S530

VIN: 1HVBRA01A911821

License Plate: 1057200

LP State: TX

Odometer Status: READABLE

Odometer Reading: 189992

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707127

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T137

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 8:07:09 AM

Test End Date/Time: Monday, June 30,
2014 8:10:08 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 9600

VIN: 1HVBRA21A911819

License Plate: 1057287

LP State: TX

Odometer Status: READABLE

Odometer Reading: 185930

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707100

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T138

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 7:51:05 AM

Test End Date/Time: Monday, June 30,
2014 7:56:10 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 1999

Make: BLUEBIRD

Model: BB38530

VIN: 1HVBBABL7XH684969

License Plate: 1091378

LP State: TX

Odometer Status: READABLE

Odometer Reading: 203159

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707098

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

7139

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, July 25,
2014 7:24:52 AM

Test End Date/Time: Friday, July 25, 2014
7:27:38 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G35707133

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: IHC

Model: AMTRAN

VIN: 1HVBRA111A911813

License Plate: 1057242

LP State: TX

Odometer Status: READABLE

Odometer Reading: 188621

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

7140

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 8:01:10 AM

Test End Date/Time: Monday, June 30,
2014 8:02:55 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: AMTRAN

VIN: 1HVBRLX1A911812

License Plate: 1057288

LP State: TX

Odometer Status: READABLE

Odometer Reading: 194426

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707099

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T141

BUS STATE INSPECTION REPORT

Bus #: T143

Tech #: Jay

Date: 06-18-13

Time: 4:00 Pm

Previous State Inspection #: 06-3

New State Inspection Cert #: 06-4



Year: 2001

Make: IHC

Model: Amtran

Vin #: 1HVBRA6L61A911810

Lic-plate #: 105-7288

Mileage: 187259

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, June 24,
2014 8:15:57 AM

Test End Date/Time: Tuesday, June 24,
2014 8:18:02 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2001

Make: INTERNATIO

Model: 9600

VIN: 1HVBRA71A911816

License Plate: 812316

LP State: TX

Odometer Status: READABLE

Odometer Reading: 202278

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707093

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

7151

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, February 28, 2014 6:44:04 AM

Test End Date/Time: Friday, February 28, 2014 6:51:06 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MAX MONDRAGON

Inspection Information

Certificate #: G30943014

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 1992

Make: WAYNE

Model: INTERNATIONAL

VIN: 1HVBCNMN5NH394021

License Plate: 1057064

LP State: TX

Odometer Status: READABLE

Odometer Reading: 135163

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T158

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
September 24, 2013 1:12:49 PM

Test End Date/Time: Tuesday, September
24, 2013 1:14:53 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CHRIS CHADDICK

Vehicle Information

Vehicle Type: School Bus

Year: 1992

Make: INTERNATIO

Model: LIFESTAR

VIN: 1HVBCNMN2NH394025

License Plate: 1057063

LP State: TX

Odometer Status: READABLE

Odometer Reading: 152019

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891192

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

7159

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, October
29, 2013 8:22:22 AM

Test End Date/Time: Tuesday, October
29, 2013 8:24:23 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus

Year: 1992

Make: INTERNATIONAL

Model: WAYNE

VIN: 1HVBCNMN7NH394022

License Plate: 1057062

LP State: TX

Odometer Status: READABLE

Odometer Reading: 182054

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942914

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T160

BUS STATE INSPECTION REPORT

Bus #: T-163

Tech #: A. McCallum

Date: 8-7-13

Time: 4:35 pm

Previous State Inspection #: G21189708

New State Inspection Cert #:



Year: 1992

Make: IHC 3900 FC

Model: W RYN5

Vin #: 1HVTBCNMN6M4394026

Lic-plate #: 103-7533

Mileage: 139332

BUS STATE INSPECTION REPORT


Bus #: 164

Tech #: 1127

Date: 8/15/13

Time: 11:33 AM

Previous State Inspection #: G16856193

New State Inspection Cert #: 
G26891169

Year: 1992

Make: IHC 3900 FC

Model: Wayne

Vin #: 1HVBCNMN9NH394019

Lic-plate #: 1037503

Mileage: 143427

TEXAS VEHICLE INSPECTION REPORT

Safety Only Inspection

VEHICLES FAILING EMISSIONS TESTS MAY BE ELIGIBLE FOR UP TO \$600 IN REPAIR ASSISTANCE. FOR MORE INFORMATION, VISIT www.driveacleanmachine.org OR CALL 1-800-913-

Vehicle Identification

Test Date/Time: 5/28/14, 10:01
Test Type: Initial
Test: Safety
Version Number: 1353
License Number: 1057216
Vehicle ID Number: 1BAAKCFH8RF057922
Vehicle Make: Bluebird
Vehicle Model: EXPEDITION 2WD
Vehicle Year/Type: 1993 / BUS
Engine Size: 0
Cylinders/Ignition: 0
Transmission/GVW: / 0
Odometer/Fuel Type: 190048 / GASOLINE

Station Identification

Station Name: ONE STOP TIRE & AUTOMOTIV
Station Number/Analyzer: 1P38760 SE290111
Station Address: 5900 INDEPENDANCE
Station City: PLANO
Station Zip Code: 75023-0000
Inspector First Name: JAMES
Inspector Last Name: CHENEY
Safety Inspection Fee: \$ 14.50
Safety Repair Costs: \$ 0.00
Total Inspection Cost: \$ 14.50

Safety Test Results

Safety Sequence: School Bus-Safety Inspection

All Items Passed

Gas Cap Integrity: PASS

Overall Result: Pass

Safety Items: PASS

Certificate Number: G32559240

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.



T168

I certify that I have properly performed the safety test according to applicable rules and regulations.

LICENSE:



VIN:



Certified Inspector's Signature

TEXAS VEHICLE INSPECTION REPORT
Safety Only Inspection

Vehicle Identification

Test Date/Time: 7/22/13, 10:06
Test Type: Initial
Test: Safety
Version Number: 0953
License Number: 1065172
Vehicle ID Number: 1BAAKCFH8KF057923
Vehicle Make: Bluebird
Vehicle Model: BUS
Vehicle Year/Type: 1993 / BUS
Engine Size: 0
Cylinders/Ignition: 0
Transmission/GVW: / 0
Odometer/Fuel Type: 189921 / GASOLINE

Station Identification

Station Name: ONE STOP TIRE & AUTOMOTIV
Station Number/Analyzer: 1P38760 / SE290111
Station Address: 5900 INDEPENDANCE
Station City: PLANO
Station Zip Code: 75023-0000
Inspector First Name: SHAUNPAUL
Inspector Last Name: BELLAH
Safety Inspection Fee: \$ 14.50
Safety Repair Costs: \$ 0.00
Total Inspection Cost: \$ 14.50

Safety Test Results

Safety Sequence: School Bus-Safety Inspection
All Items Passed

Gas Cap Integrity: PASS

Overall Result: Pass

Safety Items: PASS

Certificate Number: G12770243

Vehicles that fail the safety test must be repaired and pass a retest before a safety certificate can be issued.



G12770243

TIC9

I certify that I have properly preformed the safety test according to applicable rules and regulations.

LICENSE:



VIN:



Certified Inspector's Signature

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, March 24,
2014 6:28:25 AM

Test End Date/Time: Monday, March 24,
2014 6:32:14 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus

Year: 1996

Make: IHC

Model: CARPENTER

VIN: 1HVBBABN6TH319162

License Plate: 1065018

LP State: TX

Odometer Status: READABLE

Odometer Reading: 77348

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943026

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T178

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
October 02, 2013 2:21:30 PM

Test End Date/Time: Wednesday,
October 02, 2013 2:26:29 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CHRIS CHADDICK

Vehicle Information

Vehicle Type: School Bus

Year: 1997

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B20V1143583

License Plate: 716902

LP State: TX

Odometer Status: READABLE

Odometer Reading: 249764

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942905

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T182

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, March 31,
2014 3:11:48 AM

Test End Date/Time: Monday, March 31,
2014 3:14:34 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CARL PATTON

Vehicle Information

Vehicle Type: School Bus

Year: 1997

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B25V1143580

License Plate: 716904

LP State: TX

Odometer Status: READABLE

Odometer Reading: 229965

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943039

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T183

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, July 25,
2014 8:10:23 AM

Test End Date/Time: Friday, July 25, 2014
8:13:58 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G35707134

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 1997

Make: THOMAS

Model: MVP

VIN: 1T7HT4B27V1143578

License Plate: 1057252

LP State: TX

Odometer Status: READABLE

Odometer Reading: 205652

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, July 25,
2014 8:26:20 AM

Test End Date/Time: Friday, July 25, 2014
8:29:31 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G35707135

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 1997

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B27V1143581

License Plate: 716900

LP State: TX

Odometer Status: READABLE

Odometer Reading: 207220

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T185

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, April 30,
2013 8:38:56 PM

Test End Date/Time: Tuesday, April 30,
2013 8:44:31 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 1997

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B29V1143582

License Plate: 1057207

LP State: TX

Odometer Status: READABLE

Odometer Reading: 227864

Corrected Odometer:

Insurance Expiration: 07/01/2013

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891084

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T186

BUS STATE INSPECTION REPORT

Bus #: T-187

Tech #: DOME KASZYNSKI

Date: 7-9-2013

Time: 6:45 PM

Previous State Inspection #: G18656197

New State Inspection Cert #:



G26891133

Year: 1997

Make: THOMAS

Model: THOMAS MUP

Vin #: 1T7HT4B25V1143577

Lic-plate #: 716-908

Mileage: 257594

BUS STATE INSPECTION REPORT

Bus #: T-188

Tech #: 1132

Date: 7/25/13

Time: 4:37 a.m.

Previous State Inspection #: G-16856190

New State Inspection Cert #: _____



Year: 1997

Make: Thomas

Model: Thomas

Vin #: 1T7HT4B29V1143579

Lic-plate #: 1065129

Mileage: 201419

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, July 08,
2014 7:09:08 AM

Test End Date/Time: Tuesday, July 08,
2014 7:17:22 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MAX MONDRAGON

Vehicle Information

Vehicle Type: School Bus

Year: 1997

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B23V1143576

License Plate: 1091295

LP State: TX

Odometer Status: READABLE

Odometer Reading: 263549

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707117

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, February
06, 2014 1:00:19 PM

Overall Result: Pass

Test End Date/Time: Thursday, February
06, 2014 1:03:49 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Type: School Bus

Year: 1997

Make: THOMAS

Model: THOMAS

VIN: 1T7HT4B22V1143584

License Plate: 1057053

LP State: TX

Odometer Status: READABLE

Odometer Reading: 248830

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942998

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T190

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, March 25,
2014 12:26:08 PM

Test End Date/Time: Tuesday, March 25,
2014 12:30:40 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Inspection Information

Certificate #: G30943029

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 1999

Make: IHC3800

Model: BLUBIRD

VIN: 1HVBBABL6XH684963

License Plate: 760414

LP State: TX

Odometer Status: READABLE

Odometer Reading: 196452

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

7193

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October
31, 2013 9:55:10 AM

Test End Date/Time: Thursday, October
31, 2013 9:57:22 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus

Year: 2005

Make: IHC

Model: AMTRAM

VIN: 4DRBUAAN25B979119

License Plate: 882925

LP State: TX

Odometer Status: READABLE

Odometer Reading: 146966

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942921

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, October
28, 2013 8:50:03 PM

Test End Date/Time: Monday, October
28, 2013 8:53:55 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Inspection Information

Certificate #: G30942913

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 2005

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN95B979120

License Plate: 1065099

LP State: TX

Odometer Status: READABLE

Odometer Reading: 132114

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

T2001

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October
24, 2013 6:35:44 PM

Test End Date/Time: Thursday, October
24, 2013 6:39:50 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2005

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN05B979121

License Plate: 894062

LP State: TX

Odometer Status: READABLE

Odometer Reading: 142416

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942909

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2002

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October
24, 2013 8:05:20 PM

Test End Date/Time: Thursday, October
24, 2013 8:10:39 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Inspection Information

Certificate #: G30942910

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Vehicle Information

Vehicle Type: School Bus

Year: 2005

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN25B979122

License Plate: 882928

LP State: TX

Odometer Status: READABLE

Odometer Reading: 122986

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

T2003

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November 01, 2013 5:04:42 PM

Test End Date/Time: Friday, November 01, 2013 5:08:52 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2005

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBUAAN45B979123

License Plate: 882929

LP State: TX

Odometer Status: READABLE

Odometer Reading: 138463

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942927

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

BUS STATE INSPECTION REPORT

Bus #: T-2005

Tech #: 1142 AM

Date: 8-8-13

Time: 5:35 pm

Previous State Inspection #: _____

New State Inspection Cert #: _____



G26891162

Year: 2006

Make: IHC

Model: AMTRAN

Vin #: 4DRBUNAN26B248071

Lic-plate #: 204-639

Mileage: 127,859

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
February 05, 2014 1:47:21 PM
Test End Date/Time: Wednesday,
February 05, 2014 1:52:47 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2006
Make: IHC
Model: AMTRAN
VIN: 4DRBUAAN16B248070
License Plate: 204639
LP State: TX
Odometer Status: READABLE
Odometer Reading: 112808
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942997
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

BUS STATE INSPECTION REPORT


Bus #: 7-2007

Tech #: DAN KAFZYNSKI

Date: 8-12-2013

Time: 7:30 pm

Previous State Inspection #: NA

New State Inspection Cert #: 
G26891164

Year: 2006

Make: International

Model: AM TRAN

Vin #: 4DRBUAAN56B248072

Lic-plate #: 204-644

Mileage: 152475

BUS STATE INSPECTION REPORT

Bus #: T 2008

Tech #: Jayantha

Date: 08-08-13

Time: 9:30 Am

Previous State Inspection #: 08-3

New State Inspection Cert #: 08-4



Year: 2006

Make: IHC

Model: Amtran

Vin #: 4DRBUAAN56B248069

Lic-plate #: 204-638

Mileage: 142445

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November
22, 2013 7:35:15 PM

Test End Date/Time: Friday, November
22, 2013 7:37:37 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2007

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN27B346624

License Plate: 221515

LP State: TX

Odometer Status: READABLE

Odometer Reading: 114887

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942950

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2009

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
November 14, 2013 5:43:55 PM

Test End Date/Time: Thursday, November
14, 2013 5:45:35 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Inspection Information

Certificate #: G30942936

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2007

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN47B346625

License Plate: 221516

LP State: TX

Odometer Status: READABLE

Odometer Reading: 101204

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
September 04, 2013 8:36:26 PM
Test End Date/Time: Wednesday,
September 04, 2013 8:44:25 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus
Year: 2007
Make: IHC
Model: AMTRAN
VIN: 4DRBUAAN67B346626
License Plate: 221517
LP State: TX
Odometer Status: READABLE
Odometer Reading: 127576
Corrected Odometer:
Insurance Expiration: 09/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891177
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
September 24, 2013 5:17:17 PM

Overall Result: Pass

Test End Date/Time: Tuesday, September
24, 2013 5:20:32 PM

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Type: School Bus

Year: 2007

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN87B346627

License Plate: 221519

LP State: TX

Odometer Status: READABLE

Odometer Reading: 110011

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891193

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2012

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, July 15,
2014 10:11:40 AM

Test End Date/Time: Tuesday, July 15,
2014 10:13:10 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: IHC

Model: AMTRAN

VIN: 4DRBUAAN68B537948

License Plate: 1018328

LP State: TX

Odometer Status: READABLE

Odometer Reading: 133657

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707120

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2013

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, July
16, 2014 8:35:26 AM

Test End Date/Time: Wednesday, July 16,
2014 8:37:05 AM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIO

Model: 3600

VIN: 4DRBUAAN88B537949

License Plate: 1018278

LP State: TX

Odometer Status: READABLE

Odometer Reading: 101592

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707122

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2014

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, July 15,
2014 10:19:11 AM

Test End Date/Time: Tuesday, July 15,
2014 10:21:13 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIO

Model: AMTRAN

VIN: 4DRBUAAN48B537950

License Plate: 1018279

LP State: TX

Odometer Status: READABLE

Odometer Reading: 93019

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707121

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2015

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, July 14,
2014 1:55:47 AM

Test End Date/Time: Monday, July 14,
2014 1:59:38 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIO

Model: PB105

VIN: 4DRBUAAN68B537951

License Plate: 1016070

LP State: TX

Odometer Status: READABLE

Odometer Reading: 106150

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707119

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T 2014

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 8:54:39 AM

Test End Date/Time: Monday, June 30,
2014 8:56:16 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIO

Model: AMTRAN

VIN: 4DRBUAAN88B537952

License Plate: 1016071

LP State: TX

Odometer Status: READABLE

Odometer Reading: 102229

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707110

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2017

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, July 08,
2014 11:26:15 PM

Test End Date/Time: Tuesday, July 08,
2014 11:29:32 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIONAL

Model: CE AMTRAN

VIN: 4DRBUAANX8B537953

License Plate: 1016072

LP State: TX

Odometer Status: READABLE

Odometer Reading: 102401

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707118

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2018

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, May 30,
2014 10:30:39 AM

Test End Date/Time: Friday, May 30,
2014 10:33:59 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIO

Model: 4200

VIN: 4DRBUAAN18B537954

License Plate: 1018280

LP State: TX

Odometer Status: READABLE

Odometer Reading: 98581

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707085

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2019

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, May 30,
2014 10:56:34 AM

Test End Date/Time: Friday, May 30,
2014 10:57:41 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIO

Model: AMTRAN

VIN: 4DRBUAAN38B537955

License Plate: 1016073

LP State: TX

Odometer Status: READABLE

Odometer Reading: 99729

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707086

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2020

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, May 30,
2014 11:20:29 AM

Test End Date/Time: Friday, May 30,
2014 11:22:44 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2008

Make: INTERNATIO

Model: 3600

VIN: 4DRBUAAN58B537956

License Plate: 1018281

LP State: TX

Odometer Status: READABLE

Odometer Reading: 115112

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707087

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2021

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 8:49:23 AM

Test End Date/Time: Monday, June 30,
2014 8:51:20 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: INTERNATIONAL

Model: AMTRAN

VIN: 4DRBUAAN09B042971

License Plate: 1037427

LP State: TX

Odometer Status: READABLE

Odometer Reading: 87867

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707109

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2022

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, April 29,
2014 7:28:49 AM

Test End Date/Time: Tuesday, April 29,
2014 7:31:18 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: NAVISTAR

Model: 2674 SBA

VIN: 4DRBUAAN29B042972

License Plate: 1037426

LP State: TX

Odometer Status: READABLE

Odometer Reading: 83634

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707054

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2023

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
January 29, 2014 2:11:26 PM

Test End Date/Time: Wednesday,
January 29, 2014 2:14:49 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: INTERNATIO

Model: PB105

VIN: 4DRBUAAN49B042973

License Plate: 1018334

LP State: TX

Odometer Status: READABLE

Odometer Reading: 83460

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942984

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2024

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday, April 30, 2014 11:31:44 AM

Test End Date/Time: Wednesday, April 30, 2014 11:35:26 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: INTERNATIONAL

Model: PB-10500

VIN: 4DRBUAAN69B042974

License Plate: 1018335

LP State: TX

Odometer Status: READABLE

Odometer Reading: 89449

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707062

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2025

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, April 04,
2014 1:00:35 AM

Test End Date/Time: Friday, April 04,
2014 1:03:17 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CARL PATTON

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: IHC

Model: PB10500

VIN: 4DRBUAAN89B042975

License Plate: 1018336

LP State: TX

Odometer Status: READABLE

Odometer Reading: 103445

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30943043

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2026

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, October 01, 2013 5:05:58 AM

Test End Date/Time: Tuesday, October 01, 2013 5:08:26 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: ERIC ALLISON

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: IHC

Model: PB-10500

VIN: 4DRBUAANX9B042976

License Plate: 1018346

LP State: TX

Odometer Status: READABLE

Odometer Reading: 89738

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942903

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
October 02, 2013 3:51:14 AM
Test End Date/Time: Wednesday,
October 02, 2013 3:54:27 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus
Year: 2009
Make: IC CORP
Model: PB-10500
VIN: 4DRBUAAN19B042977
License Plate: 1018337
LP State: TX
Odometer Status: READABLE
Odometer Reading: 87415
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942901
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, October 01, 2013 5:02:48 AM

Test End Date/Time: Tuesday, October 01, 2013 5:05:18 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: ERIC ALLISON

Vehicle Information

Vehicle Type: School Bus

Year: 2009

Make: INTERNATIONAL

Model: PB10500

VIN: 4DRBUAAN39B042978

License Plate: 1018347

LP State: TX

Odometer Status: READABLE

Odometer Reading: 81507

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942902

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2029

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
December 05, 2013 6:49:39 PM
Test End Date/Time: Thursday,
December 05, 2013 6:52:40 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2009
Make: IHC
Model: IHC
VIN: 4DRBUAAN59B042979
License Plate: 1018338
LP State: TX
Odometer Status: READABLE
Odometer Reading: 82889
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942956
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T2030

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, May 30,
2014 11:36:51 AM

Test End Date/Time: Friday, May 30,
2014 11:38:04 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: C-2511

VIN: 4DRBUAAN6AB211301

License Plate: 1057134

LP State: TX

Odometer Status: READABLE

Odometer Reading: 68346

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707088

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2031

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday, June 17,
2014 6:36:54 AM

Test End Date/Time: Tuesday, June 17,
2014 6:39:46 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: INTERNATIONAL

Model: CE AMTRAN

VIN: 4DRBUAAN1AB211299

License Plate: 1057135

LP State: TX

Odometer Status: READABLE

Odometer Reading: 76520

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707102

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2032

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
September 19, 2013 2:29:39 PM
Test End Date/Time: Thursday,
September 19, 2013 2:33:09 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: CHRIS CHADDICK

Vehicle Information

Vehicle Type: School Bus
Year: 2010
Make: INTERNATIONAL
Model: C2511
VIN: 4DRBUAAN4AB211300
License Plate: 1057136
LP State: TX
Odometer Status: READABLE
Odometer Reading: 68846
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891184
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T2033

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, September 20, 2013 8:59:57 PM

Test End Date/Time: Friday, September 20, 2013 9:04:32 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: JAYANTHA
NANAYAKKARA

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: C2511

VIN: 4DRBUAAN1AB211304

License Plate: 1057137

LP State: TX

Odometer Status: READABLE

Odometer Reading: 64230

Corrected Odometer:

Insurance Expiration: 09/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891186

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2034

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, October 31, 2013 5:17:15 AM

Test End Date/Time: Thursday, October 31, 2013 5:19:13 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: MARCONY RUIZ

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: INTERNATIO

Model: PB10500

VIN: 4DRBUAAN3AB211305

License Plate: 1057138

LP State: TX

Odometer Status: READABLE

Odometer Reading: 62544

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942920

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2035

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Tuesday,
November 05, 2013 12:48:56 PM

Test End Date/Time: Tuesday, November
05, 2013 12:51:49 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: CARL PATTON

Inspection Information

Certificate #: G30942930

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: INTERNATIONAL

VIN: 4DRBUAAN8AB211302

License Plate: 1057139

LP State: TX

Odometer Status: READABLE

Odometer Reading: 60402

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2036

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, November 15, 2013 6:22:34 PM

Test End Date/Time: Friday, November 15, 2013 6:25:38 PM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus

Year: 2010

Make: IHC

Model: C2511

VIN: 4DRBUAANXAB211303

License Plate: 1057140

LP State: TX

Odometer Status: READABLE

Odometer Reading: 66958

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942941

Certificate Type: ONE YEAR SAFETY ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2037

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 30,
2014 1:16:58 AM

Test End Date/Time: Monday, June 30,
2014 1:20:33 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: PAUL VINCENT

Vehicle Information

Vehicle Type: School Bus

Year: 2011

Make: INTERNATIO

Model: 4700

VIN: 4DRBUAAN7BB356834

License Plate: 1057269

LP State: TX

Odometer Status: READABLE

Odometer Reading: 52492

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707095

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2038

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, July 21,
2014 10:13:02 AM

Test End Date/Time: Monday, July 21,
2014 10:15:57 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2011

Make: INTERNATIO

Model: 4200

VIN: 4DRBUAAN9BB356835

License Plate: 1057270

LP State: TX

Odometer Status: READABLE

Odometer Reading: 64922

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707124

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2039

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
January 29, 2014 11:03:44 AM
Test End Date/Time: Wednesday,
January 29, 2014 11:07:58 AM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: IHC
Model: CE
VIN: 4DRBUAAN7CB456000
License Plate: 1057323
LP State: TX
Odometer Status: READABLE
Odometer Reading: 39934
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942983
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Friday, May 30,
2014 11:54:00 AM

Test End Date/Time: Friday, May 30,
2014 12:00:05 PM

Overall Result: Pass

Vehicle Information

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: CE

VIN: 4DRBUAAN6CB455999

License Plate: 1091298

LP State: TX

Odometer Status: READABLE

Odometer Reading: 57297

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707089

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2041

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Monday, June 16,
2014 6:25:11 AM

Test End Date/Time: Monday, June 16,
2014 6:32:06 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: CE

VIN: 4DRBUAAN9CB456001

License Plate: 1065000

LP State: TX

Odometer Status: READABLE

Odometer Reading: 45635

Corrected Odometer:

Insurance Expiration: 07/01/2014

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707101

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2042

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday, July 17,
2014 10:03:58 AM

Test End Date/Time: Thursday, July 17,
2014 10:05:01 AM

Overall Result: Pass

Station Information

Station #: 1G020260

Station Name: PLANO ISD MOTOR POOL

Station Address: 600 SEABROOK DR
PLANO, TX 75023

Inspector Name: THOMAS MCCALLUM

Vehicle Information

Vehicle Type: School Bus

Year: 2012

Make: IHC

Model: CE

VIN: 4DRBUAAN0CB456002

License Plate: 1065001

LP State: TX

Odometer Status: READABLE

Odometer Reading: 48665

Corrected Odometer:

Insurance Expiration: 07/01/2015

Insurance Mileage Expiration:

Inspection Information

Certificate #: G35707123

Certificate Type: ONE YEAR SAFETY
ONLY

Test Type: INITIAL

Inspection Type: SAFETY

VI30 Certificate #:

Fees

Inspection Cost: \$14.50

VI30 Cost: \$0.00

Repair Cost: \$0.00

Total Cost: \$14.50

T2043

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Thursday,
September 19, 2013 8:13:11 PM
Test End Date/Time: Thursday,
September 19, 2013 8:15:15 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: IHC
Model: CE
VIN: 4DRBUAAN2CB456003
License Plate: 1065002
LP State: TX
Odometer Status: READABLE
Odometer Reading: 31400
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G26891185
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50

T2044

Texas Department of Public Safety

Vehicle Inspection Report

Test Start Date/Time: Wednesday,
October 30, 2013 9:26:57 PM
Test End Date/Time: Wednesday,
October 30, 2013 9:32:18 PM

Overall Result: Pass

Station Information

Station #: 1G020260
Station Name: PLANO ISD MOTOR POOL
Station Address: 600 SEABROOK DR
PLANO, TX 75023
Inspector Name: DAVID KASZYNSKI

Vehicle Information

Vehicle Type: School Bus
Year: 2012
Make: INTERNATIONAL
Model: CE
VIN: 4DRBUAAN4CB456004
License Plate: 1065003
LP State: TX
Odometer Status: READABLE
Odometer Reading: 43396
Corrected Odometer:
Insurance Expiration: 07/01/2014
Insurance Mileage Expiration:

Inspection Information

Certificate #: G30942919
Certificate Type: ONE YEAR SAFETY
ONLY
Test Type: INITIAL
Inspection Type: SAFETY
VI30 Certificate #:

Fees

Inspection Cost: \$14.50
VI30 Cost: \$0.00
Repair Cost: \$0.00
Total Cost: \$14.50